

Industrial Hygiene • Air Quality • Lead & Asbestos • Training • Health & Safety

2012 ASBESTOS HAZARD EMERGENCY RESPONSE ACT (AHERA) 3-YEAR RE-INSPECTION REPORT

Conducted at:

SULTANA ELEMENTARY SCHOOL 1845 SOUTH SULTANA AVENUE ONTARIO, CALIFORNIA 91761

Prepared for:

MR. CRAIG MISSO
ONTARIO-MONTCLAIR SCHOOL DISTRICT
950 WEST D STREET
ONTARIO, CALIFORNIA 91762

Prepared by:

EXECUTIVE ENVIRONMENTAL 310 EAST FOOTHILL BOULEVARD, SUITE 200 ARCADIA, CALIFORNIA 91006

> Project Number EE 12-Z0151-0010 March 30, 2012


Report assembled by:

Yesenia Galeana Technical Report Writer Executive Environmental Report generated/reviewed by:

Tim Galeana, CAC # 98-2470 Senior Project Manager Executive Environmental

TABLE OF CONTENTS

- I. EXECUTIVE SUMMARY
- II. SURVEY RESULTS REPORT
- III. SITE MAP
- IV. INSPECTOR'S CERTIFICATIONS
- V. DISCLAIMER/REPORT LIMITATIONS



1. Executive Summary

In March 2012, Executive Environmental (EE) performed a re-inspection for asbestos-containing building materials (ACBMs) at Sultana Elementary School, located at 1845 South Sultana Avenue, Ontario, California. The purpose of the re-inspection was to comply with the U.S. Environmental Protection Agency (EPA) Code of Federal Regulations, Title 40, Section 763, Asbestos Hazard Emergency Response Act (AHERA) three-year re-inspection requirement.

Prior to the re-inspection, previous inspection reports were reviewed in order to determine which building materials had been previously tested and found to contain asbestos, which materials were determined not to be asbestos-containing, and whether any materials had not been tested for asbestos.

After the review of the previous building inspections, a complete visual walk-through inspection of the site was performed. The inspection revealed that conditions at the Sultana Elementary School have changed since the last inspection in 2009. Previously unidentified materials have been added to the AHERA documentation.

Below is a list of ACBMs present within each building:

Building A

12"x12" Floor tile and mastic

Portables P1 through P8

All interior building materials are assumed to be asbestos-containing.

Portables P34, P35, P36

• All interior building materials are assumed to be asbestos-containing.

Portables F7 through F12

• All interior building materials are assumed to be asbestos-containing.

Portables PA and PB

• All interior building materials are assumed to be asbestos-containing.

Remaining asbestos-containing materials located throughout the school were intact and in good condition at the time of the re-inspection. To ensure the materials' integrity and continued good condition, periodic surveillance at six-month intervals is recommended for all materials. Material descriptions and locations can be found in Section II (Survey Results Report), along with additional information for each material.

If you have any questions, or if EE can be of further assistance, please contact our main office at (626) 441-7050.



SULTANA ELEMENTARY SCHOOL 2012 AHERA 3-Year Re-Inspection

Notes	Removed	Assumed	Removed	Removed	Removed	Removed	Removed	Removed	Removed	Removed	Negative per EE report May 2010	Under carpet and 12'x12' floor tile, Per EE report May 2010	Per EE report May 2010
Friable Cond. B Response Action		PS										PS	PS
Cond.		Ŋ										ŋ	9
Friable		No										Z	z
Type ^A		Misc.										Misc.	Misc.
Quantity		900 SF										1,000 SF	900 SF
Material	9"x9" tan floor tile	12"x12" tan floor tile	Fire-rated door	9"x9" brown floor tile	Fire-rated door	9"x9" tan floor tile	12"x12" white floor tile and associated mastic	12"x12" white floor tile and associated mastic	9"x9" brown floor tile and associated mastic	9"x9" floor tile and associated mastic	All interior materials	Flooring with black mastic	Floor tile
Location	Kitchen	Kitchen	Mechanical Room	Rooms 41 and 42	Mechanical Room	Rooms 9, 11, 12, 15, 16, 17, and 18	Room 38	Room 39	Rooms 24, 25, 26, 27, 30, 31, 32, and 33	Rooms 20, 21, and 22	Portable P37	Portable P38	Portable P39
Building	Building A (Administration)	Building A (Administration)	Building A (Administration)	Building B	Building B	Building C	Building D	Building D	Building D	Building E	Portable P37	Portable P38	Portable P39

Executive Environmental 2012 AHERA 3-Year Re-Inspection

Page 1 of 2


^A Misc. = Miscellaneous; Surf. = Surfacing; TSI = Thermal System Insulation
^B G = Good; D = Damaged; SD = Severely Damaged
^C PS = Periodic Surveillance; O&M = Operations & Maintenance Program; R = Removal

SULTANA ELEMENTARY SCHOOL 2012 AHERA 3-Year Re-Inspection

Building	Location	Material	Quantity	Type ^A Friable Cond. B Response Action ^C	riable Cc	and. ^B F	Response Action	Notes
Portables 1 through 8	Portables P1 through P8	All interior building materials	All	Misc.		9	PS	All interior building materials assumed to be asbestos containing
Portables 34, 35, 36, 37 and 39	Portables P34, P35 and P36	All interior building materials	All	Misc.		9	PS	All interior building materials assumed to be asbestos containing
Portables F7 through F12	Portables F7 through F12	All interior building materials	All	Misc.		9	PS	All interior building materials assumed to be asbestos containing
Portables PA and PB	Portables PA and PB	All interior building materials	All	Misc.		9	PS	All interior building materials assumed to be asbestos containing



Hernandez (1st) Gard (SDC 1st-3 Gammage Tompkins Cazares Duarte (2nd) Hunter Hager (3rd) Baca Smith (1st) (1st) (1st) (1st) (1st) LAS CASITAS APARTMENTS Playground Area 14/13 Counseling LUNCHAREA **10** Barnes (2nd/3rd) Velasco (2nd) Gross (2nd) Mora (2nd) Boys/Girls Restroom Storage Building 16 Serrato (3rd) Lundberg (3rd) **18** Barbee (2nd) Mejia (2nd) ThinkTogether (Apodaca) 20A DeSantis (Psychologist) Diaz (Principal) PARKING LOT Sultana Elementary Office **20** Flores (3rd) School Map **21** Hernandez, M. (3rd) Building E 2011-2012 Building A Lounge Ramirez (EA) Landis (3rd) Building Δ KINDER 42 Caldwell/Cook (K) Kinder. Playground 📑 LEARN. CNTR (Pechan) 28 Computer Lab **24** Fitzgerald (41h) Verseput (4th) **25** Alvarez (4th) Building B 26 Boys/Girls Restroom Meza-Lorenzo Viacias/Eaton Kresge (Preschool) Desantiago/ Library Peterson 33 Henley (41h) (5th) (5th) z Bush (SDC 4th-6th) Disaster Area 36 Borrowman 35 Ramirez,K. (5th) Materials **34** Styliano (61h) Morales (5th) **39** Ndicu (4th) (6th) 37 RSP 38 F10 Spencer (6th) Торјіап (5th/6th) Gillum (6th) F12 F11 etball PR urts



State of California Division of Occupational Safety and Health

Certified Asbestos Consultant



Timothy D Galeana

98-2470 Certification No.

Expires on

11/16/12

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code.

Asbestos Building Inspector Refresher Course DOSH #:CA-015-06 Tim Galeana ABIR0210120007N2015 John Brown Training Director Training and Environmental Consulting 1100 Technology Circle- Suite A, Anaheim, CA 92805 • www.natecintl.com • 800-969-3228

Important Industry Contacts

(916) 574 2993 Prix (916) 483-0572 Fax Nothication Website: Www.dircz.govycalosbra.co

KCADMD

Phul (909) 396-3739 Phili (909) 396-3347 (Fax)

NATEC International, Inc.

al Association of Training and Environmental Consulting Anahom, CA | Oakland, CA | Marianas & Guam

sbostos – Lead – Mold – HAZWOPER

P.O. Box 25205 Anahelm, CA 92825-5205 (714) 678 2750, (800) 969-3228, Fax (714) 678-2757 www.natecintl.com

NATEC International, Inc.

National Association of Training and Environmental Consulting "Nine Cards met sectors into their restricts of temperature and to me sectors as proof of This Card Acknowledges That Tim Galeana

Holds Training Certification For Asbostos Building Inspector Refresher Course (Valid for 12 months)

(Valid for 12 months)
Training Date
Certificate No ABIR0210120007N2015

John Brown

V. DISCLAIMER/REPORT LIMITATIONS

V. DISCLAIMER/REPORT LIMITATIONS

All reports and recommendations are based on conditions and practices observed and information made available to Executive Environmental (EE) by the client and the designated sites/facilities on the days the inspection was completed. This report does not purport to set forth all hazards, nor to indicate that other hazards do not exist. No responsibility is assumed by EE for the control or correction of conditions or practices existing at the facilities, or at any other premises surveyed by EE, for and on the behalf of the client. Services provided by EE shall be governed by the standard of practice for professional services measured at the time those services are rendered.

All information contained in this report is proprietary and limited to the scope of services, parameters of the analytical methods used and the conditions present at the time of this inspection. Any references to quantities are considered estimates and are not to be construed as actual.